

# Reliably Cooling Accelerators

## The Australian Synchrotron

Dr Don McGilvery  
Lead Accelerator Operator



**Australian Synchrotron**

# Reliably cooling Accelerators

Its easy, just flow some cool water through whatever you wish to cool.

But

- If there is too little flow -> melt things
- If there is too much flow -> erode things
- If the pH is too low or too high -> corrode things
- If the oxygen level is too high -> oxidise things
- If the oxygen level is too low -> strip protective oxide layer
- If the temperature is not stable -> dimensional instabilities
- If temperature is too low or too high -> leaks
- If the conductivity is too high or too low -> corrosion

At the Australian Synchrotron we have tried to implement worlds best practise to eliminate, or at least minimise the disruption caused by cooling water problems.


# Beam Availability during Scheduled User Time



**AUSTRALIAN SYNCHROTRON COMPANY LTD**

TOTAL AVAILABILITY 16-week Rolling averages


-  Total Availability
-  Machine studies
-  Maintenance
-  Shutdown





## AUSTRALIAN SYNCHROTRON COMPANY LTD


MTBF & MDT 16-week Rolling averages






## AUSTRALIAN SYNCHROTRON COMPANY LTD

Percentage of total Downtime for Last 12 months during Beamline Operations



Percentage of total Downtime since beginning (Apr 07) during Beamline Operations



- Beamlines
- Controls
- Human
- Plant
- Power (site feed)
- Power Supplies
- RF
- Vacuum

# Melted HOM Damper in SRRF Cavity





Fig. 2.4 (1) On-center damper copper sheath tip partial photograph




Fig. 2.4 (3) On-center damper tip portion (2) which melted and fell

Two of the SRRF cavities showing the extra flow meters added after the meltdown



# Flow Meters used for Storage Ring LCW



Stainless Steel construction, no moving parts, remote digital readout  
 Differential Pressure with Hall effect monitor

# Failure Modes of Flow meters

Have experienced greater than 20% failure rate


- PCB failure (change to non-Pb solder)
- Radiation Damage
- Magnet coming loose
- Earth leakage
- Failure to read Zero at zero flow
- High non-linearity
- Susceptibility to strong magnet fields

Better reliability if the meters are operated at flows near 50% flow range


Also have ongoing problems with fouling of flow control valves

Required a simple and reliable way to test meters.

# Testing Flow Meters by closing valves




# Drop in flow over a 4 day period



The trip point was 0.8 l/m


# LCW Trend GUI

(matlab script accessing EPICS database)




Select a duration and sampling interval  
 Fit a line and calculate time to **LOLO** or **HIHI**  
**Highlight** those < 4 weeks  
 Click on an entry to graph trend

# Storage Ring Low Conductivity Water Control



By changing the pressure (with no beam) it is possible to vary the flow


# Photon Stop flow meters output as overall flow reduced




## Note

- SR01 deviates low
- SR12 deviates high then fails at 50%
- There is about a 30% variation between meters

# Display of Flows and LOLO trip points




# Display of bad LOLO trip point (SR12FE01FLM04:FLOW\_STATUS)



# Plot of Flow Meter showing bad behaviour

Two days after collecting the data, (before we had analysed it) we had a beam dump caused by an intermittent flow meter trip in Front End 12.

Looking back at the flow test data it was easy to identify the suspect meter.



# Comparison of PLC set points and Observed Trip Points

The ID front end flow meters tripped at the values set in the PLCs.

(SR12FE01FLM02 didn't hit its LOLO setpoint. and SR12FE01FLM04 was **bad**)

	SR03	SR05	SR08	SR12	SR13	SR14
FE01FLM01	5.0\ 4.9	5.0\ 5.0	16.0\15.9	5.0\ 4.9	5.0\ 5.0	5.0\ 5.0
FE01FLM02	5.0\ 4.9	5.0\ 4.9	5.0\ 4.9	5.0\ NaN	5.0\ 4.9	5.0\ 4.9
FE01FLM03	16.0\16.0	16.0\15.9	16.0\16.0	6.0\15.8	16.0\15.9	16.0\16.0
FE01FLM04	5.0\ 5.0	5.0\ 4.9	16.0\15.8	5.0\ <b>26.6</b>	5.0\ 4.9	5.0\ 5.0

(PLC Trip Setpoint\Trip Value)

# Injection System Flow Switches



Stainless Steel bodies

Springs and magnets exposed to LCW

## Problems

Contamination

Plunger Sticking

Springs eroding

Magnets dissolving

Fouling of flow control valves

We will do similar testing of trip points of these switches.

## Credit

Graham Harding for suggesting to vary the pump speed to vary the flows  
Robbie Clarken for the Matlab scripts

**Australian Synchrotron**  
**[www.synchrotron.org.au](http://www.synchrotron.org.au)**



**Australian Synchrotron**