
Operator Console
control workstation
X terminal
Ethernet Lan
VME crate
profile probe


Sensor
Sensor
Sensor
< 5 m
< 5 m
< 5 m
Electronic boards
Electronic boards
Electronic boards
200 ms
Jbus link
200 ms
Jbus link
200 ms
Jbus link
G64 Acquisition crate
G64 Acquisition crate
G64 Acquisition crate
200 ms
Jbus network
RTUAX
Serial Board
Spiral Scanner Boards
VME Crate
Ethernet Lan


Graphic task
Mainloop
callback
end main loop
callback procedure
rendez-vous
end
Action task
profile command
errors tests
motif display
(high voltage
propellers status)
Refresh task
Loop
profile reading
motif display
(shapes)
end loop